

UNDERWATER BRIDGE INSPECTION REPORT

STRUCTURE NO. 30506
CR NO. 63
OVER THE
STANCHFIELD CREEK
DISTRICT 3 - ISANTI COUNTY



PREPARED FOR THE
MINNESOTA DEPARTMENT OF TRANSPORTATION
BY
COLLINS ENGINEERS, INC.
JOB NO. 3512 (CEI 74)

MINNESOTA DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION

REPORT SUMMARY:

The substructure units inspected at Bridge No. 30506, Piers 1 and 2, were found to be in good condition with no defects of structural significance observed. The timber piles were in good condition and exhibited only minor checking. The channel bottom appeared stable with no evidence of significant scour or appreciable changes since the previous inspection.

INSPECTION FINDINGS:


- (A) The timber piles at both piers were in good condition with minor checking up to 1/4 inch in width.
- (B) The timber bracing located between the easternmost piles of Pier 2 exhibited minor cracking and wood shims have been placed between the piles and the bracing, apparently in an effort to tighten the connections.
- (C) A large amount of grassy vegetation was observed at the upstream nose of Pier 1.

RECOMMENDATIONS:

- (A) Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of five (5) years.

I hereby certify that this plan, specification, or report was prepared by me or under my direct supervision and that I am a duly Licensed Professional Engineer under the laws of the State of Minnesota.

Daniel G. Stromberg




A large, stylized handwritten signature in black ink, appearing to read 'Dan Stromberg', is written over two horizontal lines.

Date 6/30/2004 Registration No. 21491

Respectfully submitted,

COLLINS ENGINEERS, INC.



A large, stylized handwritten signature in black ink, appearing to read 'Dan Stromberg', is written over two horizontal lines.

Daniel G. Stromberg
Registered Professional
Engineer, State of Minnesota

MINNESOTA DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION

1. BRIDGE DATA

Bridge Number: 30506

Feature Crossed: The Stanchfield Creek

Feature Carried: CR No. 63

Location: District 3 - Isanti County

Bridge Description: The bridge superstructure consists of three spans of timber deck and stringers that are supported by two timber piers and two timber abutments. The piers are numbered 1 and 2 starting from the south end of the bridge. Each pier consists of a timber pier cap supported by eight timber piles.

2. INSPECTION DATA

Professional Engineer/Team Leader: Shirley M. Walker, P.E.

Dive Team: Michelle D. Koerbel, Clayton G. Brookins

Date: September 25, 2002

Weather Conditions: Rainy, " 50E F

Underwater Visibility: " 2 Feet

Waterway Velocity: Negligible

3. SUBSTRUCTURE INSPECTION DATA

Substructure Inspected: Piers 1 and 2

General Shape: Each pier consists of a timber pier cap supported by a single row of eight timber piles. Timber cross bracing interconnects the piles.

Maximum Water Depth at Substructure Inspected: Approximately 5 feet.

4. WATERLINE DATUM

Water Level Reference: Top of the pile cap at the west end of Pier 1.

Water Surface: The waterline was approximately 6.5 Feet below reference.
Waterline Elevation = 932.0.

5. NBIS CODING INFORMATION (Minnesota specific codes are used for 92B and 113)

Item 60: Substructure: Code 7


Item 61: Channel and Channel Protection: Code 7

Item 92B: Underwater Inspection: Code B/09/02

Item 113: Scour Critical Bridges: Code O/02

Bridge is scour critical because abutment or pier foundation is rated as unstable due to observed scour at bridge site.

_____ Yes X No



SOUNDING PLAN



TYPICAL END VIEW OF PIERS

- Legend**
- 4.0 Sounding Depth from Waterline (9/25/02)
 - 3.5 Sounding Depth from Waterline (10/6/02)
 - Timber Pile (under pile cap)
 - Timber Pile
 - ↓ Grassy Vegetation


GENERAL NOTES:

1. Piers 1 and 2 were inspected underwater.
2. At the time of inspection on September 25, 2002, the waterline was located approximately 6.5 feet below the top of the pile cap at the upstream end of Pier 1. This corresponds with a waterline elevation of 932.0 based on the previous report dated October 6, 1992.
3. Soundings indicate the water depth at the time of inspection and are measured in feet.
4. Soundings were taken parallel to the bridge at the mid points between the substructure units.


INSPECTION NOTES:

- ① The channel bottom consisted of 6- to 8-inch-diameter cobbles with 1 inch of penetration.
- ② The timber piles exhibited minor checking up to 1/4 inch wide.
- ③ The timber bracing located between the easternmost piles exhibited minor cracking and wood shims have been placed between the piles and the bracing.
- ④ A large amount of grassy vegetation was observed at the upstream nose of Pier 1.
- ⑤ The upstream pile was protected with a steel ice breaker.

MINNESOTA DEPARTMENT OF TRANSPORTATION UNDERWATER BRIDGE INSPECTION		
STRUCTURE NO. 30506 OVER STANCHFIELD CREEK DISTRICT 3, ISANTI COUNTY		
INSPECTION AND SOUNDING PLAN		
Drawn By: PRH	COLLINS ENGINEERS, INC.	Date: AUG. 2002
Checked By: MDK	300 W. WASHINGTON, STE. 600 CHICAGO, ILLINOIS 60606 (312) 704-9300	Scale: NTS
Code: 35I20074		Figure No.: 1



UPSTREAM FASCIA PROFILE



DOWNSTREAM FASCIA PROFILE

Note:
Refer to Figure 1 for General Notes.

MINNESOTA DEPARTMENT OF TRANSPORTATION UNDERWATER BRIDGE INSPECTION		
STRUCTURE NO. 30506 OVER STANCHFIELD CREEK DISTRICT 3, ISANTI COUNTY		
UPSTREAM AND DOWNSTREAM FASCIA PROFILES		
Drawn By: PRH	 COLLINS ENGINEERS, INC. 300 W. WASHINGTON, STE. 600 CHICAGO, ILLINOIS 60606 (312) 704-9300	Date: AUG. 2002
Checked By: MDK		Scale: 1/16"=1'
Code: 35I20074		Figure No.: 2



Photograph 1. Overall View of Structure, Looking Southwest.



Photograph 2. View of Pier 1, Looking Northeast.



Photograph 3. View of Pier 2, Looking Southwest.



Photograph 4. View of the Vegetation at Pier 1, Looking South.

MINNESOTA DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGES AND STRUCTURES

UNDERWATER INSPECTION CONDITION RATING FORM

BRIDGE NO. 30506
INSPECTORS Collins Engineers, Inc.
ON-SITE TEAM LEADER Shirley M. Walker, P.E.
WATERWAY CROSSED The Stanchfield Creek

INSPECTION DATE September 25, 2002
NOTE: USE ALL APPLICABLE CONDITION DEFINITIONS AS DEFINED IN THE MINNESOTA RECORDING AND CODING GUIDE INCLUDING GENERAL, SUBSTRUCTURE, CHANNEL AND PROTECTION, AND CULVERTS AND WALL DEFINITIONS TO COMPLETE THIS FORM.

CONDITION RATING

UNIT REFERENCE NO.	UNIT DESCRIPTION	MAXIMUM DEPTH OF WATER	SUBSTRUCTURE					CHANNEL					GENERAL						
			PILING	COLUMNS, SHAFTS, OR FACES*	FOOTINGS	DISPLACEMENT	OTHER (BRACING)	OVERALL SUBSTRUCTURE CONDITION CODE*	SCOUR	EMBANKMENT EROSION	EMBANKMENT PROTECTION	OTHER (DRIFT/DEBRIS)	OVERALL CHANNEL & PROTECTION CONDITION	CONCRETE	STEEL	TIMBER	LOSS OF SECTION	PREVIOUS REPAIR OR MAINTENANCE	OTHER
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
	Pier 1	5.0'	7	N	N	9	7	7	8	N	N	7	7	N	N	7	N	N	N
	Pier 2	5.0'	7	N	N	9	6	7	8	N	N	8	8	N	N	7	N	7	N

*UNDERWATER PORTION ONLY

REMARKS: Overall, the timber piles at both piers were in good condition with minor checking up to 1/4 inch in width. The timber bracing located between the easternmost piles of Pier 2 exhibited minor cracking and wood shims have been placed between the piles and the bracing for repair measures. A large amount of vegetation was observed at the upstream end of Pier 1.

NOTES: ATTACH SKETCHES AS NEEDED, IDENTIFY REMARK BY REFERRING TO UNIT REFERENCE NO. AND REMARK NO. USE GENERAL SECTION TO IDENTIFY OVERALL PRESENCE OF SPALLS, CRACKS, CORROSION, ETC.