

Regarding HydInfra Training for Pre-qualified Consultants who do 13.1 [Detailed Inspection and Location of Stormwater System Features \(Level 1\)](#) or [13.2 Video Inspection of Stormwater System Features \(Level 2\)](#) or inspections for construction project design:

Bonnie Peterson trains consultants to do HydInfra inspection and condition rating, in person, soon after they ask to be trained. HydInfra Training has been done at several locations around the State, but usually at the [Shoreview Training Center](#). HydInfra training is focused on parts the consultants say they need, but basic HydInfra training is always primary. Other specific information consultants need (data formatting, for example) is available on the HydInfra webpages <http://www.dot.state.mn.us/bridge/hydraulics/hydinfra.html>

Training for consultants happens after consultants get a contract, and is not a requirement to become pre-qualified. Reason is: some pre-qualified contractors may be on the list for a long time before they get a contract, so if the consultant is trained after they get a contract, the HydInfra concepts will be remembered during inspections.

The most recent HydInfra Training for consultants (May 2016) included this: [Information links and Agenda for HydInfra Consultant Training 2016](#) with a focus on the inspection manual and materials. A version of this PowerPoint: [Illustrated Guide to the HydInfra Manual 2016](#) (PDF) was presented in the training.

Find **Pre-Qualification Program Work Types 13.1 GPS inspection, 13.2 video inspection, 13.3 storm drain cleaning** at <http://www.dot.state.mn.us/consult/worktypes.html>. HydInfra Training is not required for 13.3 Cleaning.

Bonnie Peterson
HydInfra Coordinator
Office Phone: 651-366-4470
bonnie.peterson@state.mn.us

MnDOT Bridge
Hydraulics Unit
MS 610
3485 Hadley Ave. N.
Oakdale, MN 55128